




FIG. 1







b0	b1	b2	b3	x0	x1	x2	хЗ	х4	х5	х6	x7	х8	х9	x10	x11
0	0	0	0												
0	0	0	1	1											
0	0	1	0		1										
0	0	1	1			1									
0	1	0	0				1								
0	1	0	1					1							
0	1	1	0						1						
0	1	1	1							1					
1	0	0	0								1				
1	0	0	1									1			
1	0	1	0										1		
1	0	1	1											1	
1	1	0	0												1

FIG. 5

$$B3 = X0 + X2 + X4 + X6 + X8 + X10$$

$$B2 = X1 + X2 + X5 + X9 + X10$$

$$B1 = X3 + X4 + X5 + X6 + X11$$

$$B0 = X7 + X8 + X9 + X10 + X11$$

FIG. 6